

Draft




- Approximate Area Requiring Soil Cleanup
- Approximate Area Requiring Ground Water cleanup
- Approximate Site Boundary, queried where uncertain
- Excavation Area, Ecology, 1994
- Excavation Area, Parametrix, 1989
- Former UST Location
- 8" Diameter Water Main
- Abandoned Wooden Drainage Culvert
- Buried Culvert

Figure 12
Areas Requiring Cleanup
Hansville General Store



0 30 60 90
Feet



DEPARTMENT OF
ECOLOGY
State of Washington